C4 HEBBALA

ಬೆಂಗಳೂರು ವಿದ್ಯುತ್ ಸರಬರಾಜು ಕಂಪನಿ ನಿಯಮಿತ

BESCOM YQ

7910766

Receipt Number	167279401974
Reciept Date	26-02-2018 14:53:06
Cash Counter	BESCOM- C4, Office counter
Payor Account ID	1672794579
Person Name	AEE BBMP
RR Number	
Total Payment	Rs12,240.00
Mode of pay	Draft
Cheque /DD No	577022
Bank Name	FEDERAL BANK
Purpose	Deposits
Non Revenue category	ZMMD-FEE

ಕಛೇರಿ ಮೊಹರು

Twelve Thousand Two Hundred Forty Rupees Only

Payment verified 26/2/18

---------- THANK YOU ----------

ನಗದು ಗುಮಾಸ್ತರ ಸಹಿ

Manu Enterprises

C4 HEBBALA

ಬೆಂಗಳೂರು ವಿದ್ಯುತ್ ಸರಬರಾಜು ಕಂಪನಿ ನಿಯಮಿತ

BESCOM YQ

7910768

Receipt Number	485516592154
Reciept Date	26-02-2018 14:53:06
Cash Counter	BESCOM- C4, Office counter
Payor Account ID	4855165235
Person Name	AEE BBMP
RR Number	
Total Payment	Rs8,160.00
Mode of pay	Draft
Cheque /DD No	577022
Bank Name	FEDERAL BANK
Purpose	Deposits
Non Revenue category	ZMMD-FEE

ಕಛೇರಿ ಮೊಹರು

Eight Thousand One Hundred Sixty Rupees Only

Payment verified 26/2/18

---------- THANK YOU ----------

ನಗದು ಗುಮಾಸ್ತರ ಸಹಿ

Manu Enterprises

C4 HEBBALA

ಬೆಂಗಳೂರು ವಿದ್ಯುತ್ ಸರಬರಾಜು ಕಂಪನಿ ನಿಯಮಿತ

BESCOM YQ

7910767

Receipt Number	435781364123
Reciept Date	26-02-2018 14:53:06
Cash Counter	BESCOM- C4, Office counter
Payor Account ID	4357813925
Person Name	AEE BBMP
RR Number	
Total Payment	Rs1,640.00
Mode of pay	Draft
Cheque /DD No	577022
Bank Name	FEDERAL BANK
Purpose	Deposits
Non Revenue category	ZMMD-FEE

ಕಛೇರಿ ಮೊಹರು

One Thousand Six Hundred Forty Rupees Only

payment verified 26/2/18

ನಗದು ಗುಮಾಸ್ತರ

Manu Enterprises

WATER WELLS

Specialist in : Ground Water Exploration, Development, Management and Rejuvenation

GEOLOGICAL - GEOHYDROLOGICAL - GEOPHYSICAL REPORT

V. APRAMEYA MURTHY, B.Sc (HONS), M.Sc
Ex-Officio RDPR, Department
744, 7th A Cross, A Sector
Yelahanka New Town, Bangalore - 560 064.

MOB : 94484 19262
RES : 080-28561744

Date : 4/2/18

1. Name : KRIDL		
2. Address : BANGALORE Survey No.:	Taluk :	Bangalore
	Dist :	Bangalore
3. Topography of the area.		Plain Terrain
4. Geology of the area.		Gneissic
5. Geohydrological condition of the area		Moderate
6. Survey conducted for	A. Type of Area	Agriland / Site / Layout /
	B. Purpose	Irrigation / Domestic / Water Supply
7. Method of Survey Employed :		Geological - Geophysical - Geohydrological
8. RECOMMENDATION	A. Type of well	$6\frac{1}{2}$" Dia Bore well
	B. Location	Shown
	C. Depth	850 ft
	D. Probable casing	120 to 140 ft
9. YIELD EXPECTED*		2"
10. SPECIAL RECOMMENDATION IF ANY		Outer P.V.C. Casing is required

*Conditions Apply.

For WATER WELLS

Geologist

No: S.S./GPS/GHI/110/2005-06.

Siradi Sai Ground Water
Survey and Investigation
No. 19, "SRI SAIKRUPA"
21st Main, 3rd 'B' Cross,
BTM 2nd Stage,
Bangalore-560076.
Mobile- 9845787110.

Dated: 13/2/2018

To,

Sri/ Smt: KRIDL
BANGALORE.

Sir,

Sub:- Report of Geophysical & Geo – Hydrological Investigation.

Geo-hydrological Survey and Geophysical resistivity Investigation was carried out as per your request dated 13/2/18.. in your Land / Site survey / Site No..... Located at SAHKAR NAGAR Village, ...taluk, BANGALORE District, on dated..13/2/18order to assess the ground water potential of the area for drinking / industrial purpose. The observations and recommendations are as follows.

1. From the study of the field observations together with the Geo-hydrological Survey / Geophysical resistivity investigation result a bore well of 175 mm diameter is recommended for drilling at site no. ..... to a depth of ..400 to ..500.. / ft below the ground level casing pipe required to a depth of ..120 to 140..ft below ground level. The selected site was show to Sri/ Smt. VARUN.B.R..... yield ..1".... to ..... GPH.

2. Although the best site for drilling has been suggested, no guarantee of success can be given and the agency will not be responsible in any way for any loss to the party in respect of the B.W. drilled at the site recommended being a failure.

3. The Geophysical and Geo-hydrological survey has revealed that the area is fusible for borewell due to sufficient ground water potential.

Yours faithfully
Thopegowda.
(DIVINER)

No: S.S./GPS/GHI/110/2005-06.

Siradi Sai Ground Water
Survey and Investigation
No. 19, "SRI SAIKRUPA"
21st Main, 3rd 'B' Cross,
BTM 2nd Stage,
Bangalore-560076.
Mobile- 9845787110.

Dated: 12/2/2018

To,

Sri/ Smt: KRIDL
BANGALORE

Sir,

Sub:- Report of Geophysical & Geo – Hydrological Investigation.

Geo-hydrological Survey and Geophysical resistivity Investigation was carried out as per your request dated 12/2/2018 in your Land / Site survey / Site No..... Located at SAHKAR NAGAR Village, ...taluk, BANGALORE.....District, on dated.12/2/2018order to assess the ground water potential of the area for drinking / industrial purpose. The observations and recommendations are as follows.

1. From the study of the field observations together with the Geo-hydrological Survey / Geophysical resistivity investigation result a bore well of 175 mm diameter is recommended for drilling at site no. ..... to a depth of .900 to .1000. / ft below the ground level casing pipe required to a depth of .140 to 160...ft below ground level. The selected site was show to Sri/ Smt. VARUN.B.R yield .1.1/2". to ...2..... GPH.

2. Although the best site for drilling has been suggested, no guarantee of success can be given and the agency will not be responsible in any way for any loss to the party in respect of the B.W. drilled at the site recommended being a failure.

3. The Geophysical and Geo-hydrological survey has revealed that the area is fusible for borewell due to sufficient ground water potential.

Yours faithfully
Thopegowda
(DIVINER)

|| Sri Veeranna Gowda Prasanna ||

ಶ್ರೀ ಲಕ್ಷ್ಮೀ ಬೋರ್‌ವೆಲ್ಸ್ ಮತ್ತು ಅರ್ಥ್‌ಮೂವರ್ಸ್

SRI LAKSHMI BOREWELLS & EARTH MOVERS

Dealers in : All Kinds of Irrigation & Domestic Pumps
Fast Drilling & Re-Drilling Contractors
Opp. Big Market, Sahakaranagar, Airport Road, Byatarayanapura, Bangalore - 92.
Mob. : 9845404291

Ref. :

Date : 17/2/18

TO: KRIDL
BANGALORE

Sub: well completion Report

a) Drilling Strated date 17/2/2018

b) closing date 17/2/2018

c) casing pipe Erection 120 ft Feet

d) Borewell drilling 600 Ft depth Feet

e) Water First Source 250 dt — 1000 GPH

d) IInd Source 600 dt — 1000 gph

e) defects on the Bore well
light silt & small Boudrers

d) ~~Soil~~ Rock colour white & Red

For SRI LAKSHMI BOREWELLS & EARTH MOVERS

Proprietor

|| Sri Veeranna Gowda Prasanna ||



ಶ್ರೀ ಲಕ್ಷ್ಮೀ ಬೋರ್‌ವೆಲ್ಸ್ ಮತ್ತು ಅರ್ಥ್‌ಮೂವರ್ಸ್

SRI LAKSHMI BOREWELLS & EARTH MOVERS

Dealers in : All Kinds of Irrigation & Domestic Pumps
Fast Drilling & Re-Drilling Contractors

Opp. Big Market, Sahakaranagar, Airport Road, Byatarayanapura, Bangalore - 92.
Mob. : 9845404291

Ref. :

Date : 15/2/2018

To, KRIDL
BANGALORE

Sub: Borewell completion Report.

a) Drilling started work date 15/2/2018

b) Drilling closing work date 15/2/2018

c) M.S. Casing pipe Erection Borewell ____

d) Borewell drilling depth of Borewell 1300FT

e) dia of the Borewell 6 1/2

d) 10 pvc outer pipe Erection ____

g) waters Source of the Borewell. 400 1st Source Lagio

h) waters Source of the Borewell 600 IInd source

i) deatects of the Borewell Light Silt.

k) Rock colour Brown

For SRI LAKSHMI BOREWELLS & EARTH MOVERS

Proprietor

For SRI LAKSHMI BOREWELLS & EARTH MOVERS

Proprietor

|| Sri Veeranna Gowda Prasanna ||



ಶ್ರೀ ಲಕ್ಷ್ಮೀ ಬೋರ್‌ವೆಲ್ಸ್ ಮತ್ತು ಅರ್ಥ್‌ಮೂವರ್ಸ್

SRI LAKSHMI BOREWELLS & EARTH MOVERS

Dealers in : All Kinds of Irrigation & Domestic Pumps
Fast Drilling & Re-Drilling Contractors

Opp. Big Market, Sahakaranagar, Airport Road, Byatarayanapura, Bangalore - 92.
Mob. : 9845404291

Ref. :

Date : 16/2/18

TO: KRIDL
BANGALORE

Sub: Borewell completion Report

a) Drilling Start the work 16/2/18

b) Drilling closing the work 16/2/18

c) MS casing pipe & the Erection ———

d) Borewell drilling total depth 300 ft

e) water Source Ist 120 ft Level

g) water IInd Source 200 ft Level

h) 10' PVC outer pipe Erection ———

i) Rock colour of the Stone white & Red.

g) defects of the Bore well Silt.

For SRI LAKSHMI BOREWELLS
& EARTH MOVERS

Proprietor